STATE OF WEST VIRGINIA Department of Environmental Protection Environmental Enforcement

NOTICE OF VIOLATION

Violation No <u>W18-19-047-TAG</u>

To the Operator or Agent of: Facility Name: <u>RAN 5 Project</u> Permit No. <u>WVR108876</u> Permittee or Individual: <u>ROXUL USA INC.</u> Located at or near: <u>Ranson, in Jefferson</u> County Representative: <u>KENNETH J. CAMMARATO</u> Date: <u>09/11/18</u> Time: 3:00pm Address / phone number: <u>4594 CAYCE RD, BYHALIA, MS 38611 / 6628514734</u>

Whereas, an inspection of the above named operation by the undersigned, duly authorized agent of the Secretary, at which the following described condition or practice exists, in violation of Chapter <u>22</u>, Article <u>11</u>, Section(s) <u>1 et. Seq.</u> of the Code of West Virginia and/or Section(s) <u>of the Rules and Regulations and/or Section(s) (D., F., & G.)</u> of the Permit referenced above promulgated thereunder in that you: <u>Have violated the following terms and conditions of WV/NPDES General Water Pollution Control Permit No.</u> <u>WV0115924, Registration No. WVR108876:</u>

<u>1. Section D.1. - Permittee has failed to properly operate and maintain all systems of treatment and controls- Drop inlets near the central area of the project are in need of maintenance.</u>

2. Section G.4.e.2. - Permittee has failed to properly implement controls: Filter sock improperly installed. SWPPP plan calls for triple stack filter sock at the end of the rock outlet protection for sediment basin 1.

<u>3. Section G.4.e.2.A.ii.c. - Permittee has failed to provide inlet protection for sediment control structure near the forebay of SB 1.</u>

4. Section G.4.e.2.A.ii.f. - Permittee has failed to protect fill slopes near the forebay of SB 1.

5. Section G.4.e.2.A.i.b. - Failed to provide interim stabilization on areas where construction activities have temporarily ceased for more than 14 days. Area noted was near the forebay of Basin 1.

<u>6. Section F.2.a. - Failed to report noncompliance, which may have endangered health or the environment, to the designated WVDEP spill alert telephone number (800-642-3074). Sinkhole was observed in basin 1 and was not reported.</u>

The following corrective measures were discussed with you at the time of this inspection. I spoke with Chip Mullenex on 09/25/18 of findings:

Take measures to correct the aforementioned violations.

Within <u>20</u> days provide a written response to the inspector named below, at the address indicated, detailing the actions taken to abate this violation.

 Received by:
 Sent Certified Mail--70180040000047937006

 Signature
 Title

 Jang M.Jug
 Tommy.a.george@wv.gov

 Duly Authorized Agent / Inspector
 304-703-5320

 Telephone
 E-mail

 Send Response to the Inspector at the address indicated below:

 WV Department of Environmental Protection

 Environmental Enforcement / WW

22288 Northwestern Pike, Romney, WV 26757-8005



