



**OFFICE OF ENVIRONMENTAL REMEDIATION**  
**VOLUNTARY REMEDIATION PROJECT**  
**SITE VISIT/INSPECTION REPORT**

**APPLICANT**

**LRS**

NAME: : <b>Freedom Industries</b>			NAME: <b>Matt Ford</b>			LRS# <b>240</b>					
ADDRESS: <b>1015 Barlow Drive</b>			ADDRESS: <b>533 North Jefferson Street, Suite 3</b>								
CITY: <b>Charleston</b>		STATE: <b>WV</b>		ZIP: <b>25311</b>		CITY: <b>Lewisburg</b>		STATE: <b>WV</b>		ZIP: <b>24901</b>	
PHONE: <b>(304)720-2312</b>						PHONE: <b>(304) 520-4260</b>					
CONTACT: <b>Robert Johns, Spill Claim Plan Administrator</b>											

**LOCATION**

FACILITY: : <b>Freedom Industries</b>			STREET ADDRESS: : <b>1015 Barlow Drive</b>								
CITY: <b>Charleston</b>			COUNTY: <b>Kanawha</b>			PHONE: ( )					
DATE OF VISIT: <b>March 07, 2016</b>				TIME IN: <b>2:22</b>				TIME OUT: <b>2:48</b>			

**SITE STATUS:** Abandoned  Active  | **UST's:** Existing  Former  | **SURFACE SOIL STAINING:** Yes  No   
**SURFACE WATER ON OR ADJACENT TO PROPERTY:** Yes  No  | **EXISTING MONITORING WELLS:** Yes  No

Existing Structures Including Dimensions and Use: Former/current office building composed of offices, small coal testing lab and storage approximately 125' Length x 85' wide x 30' in height. Garage and maintenance/vehicle storage building approximately 225' in length x 55' wide x 20' in height.

Chemicals of Potential Concern: 4-methylcyclohexanemethanol (MCHM), propylene glycol phenyl ether (PPH), calcium chloride, ethylene glycol, glycerin, polychlorinated biphenyls (PCB's), lead, petroleum hydrocarbons, volatile organic compounds (VOC's) and semi-volatile organic compounds (SVOC's)

<b>DRINKING WATER SOURCE:</b> GW <input type="checkbox"/> Public <input checked="" type="checkbox"/> Other			<b>SURROUNDING LAND USE:</b> Residential <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Recreational <input type="checkbox"/> Agricultural <input type="checkbox"/> Other <input type="checkbox"/>								
---	--	--	--	--	--	--	--	--	--	--	--

**OTHER AREAS OF CONCERN:**

**COMMENTS**

Time in at Freedom was 14.22.

Personnel on site were were Kinder Tuckwiller of Core Environmental, Lance Wilcox, Gary Houseman and Larry Cafken who were operating the backhoe equipment. Soil was being redistributed in cut-off trench area on lower level. Area was extremely muddy and equipment was having difficulty operating.

No water was removed today.

6 loads of contaminated soil from area 4 removed last Friday.

Soil currently being redistributed in trench area did exhibit some MCHM odor according to Kinder and was being stockpiled on lower level until a desion is reached for either disposal or placement under cap. Faint petroleum odor still present at site. Scheduled to abandon #13 monitoring well.

Cap placement is scheduled to begin later this week.

Departed site at 14:48.

*Danae Hight*

3/08/16

**Signature:** \_\_\_\_\_ **Date:** \_\_\_\_\_



Figure 1: Equipment working in lower trench area



Figure 2: Soil found to contain MCHM in trench area being stockpiled to left of excavator




Figure 3: MCHM contaminated soil from area 4 has been removed

Signature: \_\_\_\_\_

Date: \_\_\_\_\_