

West Virginia Department of Environmental Protection

2022 AML Contract 8 Project North Project Overview CEOI 0313 DEP2200000017



Presented By:

Daniel Martinez, P.E.


December 13, 2022

Disclaimer

- Civil & Environmental Consultants, Inc. (CEC) is currently pursuing the Contract 8 Project North EOI and therefore has not yet been awarded the project.
- Photos and information presented herein obtained from a combination of WVDEP provided data and field evidence observed by CEC from site walkthrough held on November 1, 2022.
- All profiles and design information presented are to be considered conceptual in nature and are intended only to depict potential approaches to mitigation alternatives.




Contract 8 North - Site Location



STATE VICINITY MAP




Contract 8 North - Site Description





Contract 8 North Existing Hazards - Highwalls

• Priority 2 Highwalls - ~5,500 LF-30-90 ft heights



Contract 8 North Existing Hazards – Refuse Pile

- Exposed refuse pile
 - ~40,000 CY of refuse anticipated for removal

ASSUMED NATURAL GRADE

2+00

NOTE: ALL PROFILES AND DESIGN INFORMATION PRESENTED ARE TO BE CONSIDERED CONCEPTUAL IN NATURE AND ARE INTENDED ONLY TO DEPICT POTENTIAL APPROACHES TO MITIGATION ALTERNATIVES

1+00

1280

1260

1240


1220

1200

1180

0+00

ELEVATION




Project Location Map - Topographic Map Brownton Refuse #2, WV-3242



Contract 8 North Existing Hazards – Water Bodies

2 Dangerous Water Bodies




Project Location Map - Topographic Map Brownton Refuse #2, WV-3242 Legend East Water Body - Access Road Project Area **AML Points** Dangerous Impoundment Hazardous Water Body **AML Lines** Clogged Stream Dangerous Highwalls Highwall **AML Polygons** Dangerous Piles and Embankments West Water Body




Contract 8 North Existing Hazards – Mine Portals

1 known portal and 1 suspected portal



Project Location Map - Topographic Map Brownton Refuse #2, WV-3242






Contract 8 North Existing Hazards – Clogged Stream

• Clogged stream and culvert to be cleared and lined with limestone



NOTE: ALL PROFILES AND DESIGN INFORMATION PRESENTED ARE TO BE CONSIDERED CONCEPTUAL IN NATURE AND ARE INTENDED ONLY TO DEPICT POTENTIAL APPROACHES TO MITIGATION ALTERNATIVES





Contract 8 North Anticipated Mitigation Actions

- SUMMARY OF MITIGATION ACTIONS
 - Relocation of surface gas line
 - Site wide regrading of benches and highwalls
 - Drainage improvements and regrading of existing water bodies
 - Installation of limestone drainage features
 - Mine portal sealing
 - Site access improvements

NOTE: ALL PROFILES AND DESIGN INFORMATION PRESENTED ARE TO BE CONSIDERED CONCEPTUAL IN NATURE AND ARE INTENDED ONLY TO DEPICT POTENTIAL APPROACHES TO MITIGATION ALTERNATIVES



Questions?

CONNECT WITH US!













www.cecinc.com

